

FIG. 1A




FIG. 1B




FIG. 1C




FIG. 2A




FIG. 2B




FIG. 3




FIG. 4A




FIG. 4B




FIG. 5




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 7A




FIG. 7B




FIG. 8




FIG. 9A




FIG. 9B





FIG. 9C






FIG. 10





FIG. 11B
1g CUTTING PART SLIT-FORMED FERRULE






FIG. 12

FIG. 13A




FIG. 13B




FIG. 14A




FIG. 14B





FIG. 14C






FIG. 15

FIG. 16A




FIG. 16B




FIG. 17 RELATED ART

23/24

